

## APPENDIX 3

### ANALYSIS OF HACKNEY CARRIAGE VEHICLE FAILURES

January 2010 to December 2010

<b>Fault</b>	<b>No. Failures</b>	<b>Main failures</b>
<b>Lighting Equipment</b>	<b>117</b>	<b>Headlamp aim &amp; bulbs</b>
<b>Steering &amp; Suspension</b>	<b>132</b>	<b>Track rod ends, steering box/gaiter</b>
<b>Brakes</b>	<b>62</b>	<b>Hoses and brake test</b>
<b>Tyres &amp; Wheels</b>	<b>41</b>	<b>Tyre tread below limit and damage</b>
<b>Seatbelts</b>	<b>12</b>	<b>Not working properly</b>
<b>General</b>	<b>161</b>	<b>Windscreen glass, washers/wipers</b>
<b>Total</b>	<b>525</b>	