Date of tour Biscot Ward	Ref	Location	Issue	Action – Referred to	Outcome
11/8/14	1.	Blenheim Crescent Chaucer Road Argyle Avenue	Street Cleaning – The roads mentioned and others off Biscot Road. Detailed cleaning is not taking place and it is evident that brush cleaning is not taking place. •Members have asked that arrangement be made to allow for sweeping i.e. •Notify residents. •Co-ordinated approach with parking, cleansing and enforcement. •The whole ward needs to be looked at very carefully.	Alex Greene	
11/8/14	2.	Trees at the above locations and other areas identified with Tree outside 94. Alexandra Avenue	Prune Reduce crowns	Barry Timms Robbie Barnes	
11/8/14	3.	Milk Shake Town	Shop on the corner of Blenheim Crescent and Biscot Road operating as a retail outlet and outside of the regulation	Jackie Barnell LBC Planning Division	

Date of tour Biscot Ward	Ref	Location	Issue	Action – Referred to	Outcome
11/8/14	4.	1. Blenheim Crescent	No dropped kerb and pavement outside the house all cracked.	Stuart Jackson LBC Highways & Engineering	Passed to inspector to investigate. Ref 810331. Car not present at time of visits. Hence we are unable to prove this illegal crossing is occuring. The cracked paving in the area does not meet our criteria for repair. S Jackson 18.08.2014
11/8/14	5.	Blenheim Crescent Cash point machine on the corner of the above and Biscot Road.	Divers parking their cars close to the junction and up on the kerb. • Can bollards at this location be considered?	Stuart Jackson LBC Highways & Engineering	Waiting restrictions are in place at this location. It is an issue for Parking Enforcement. Bollards are expensive to put in and represent a constant maintanence problem. Governement policy is also to reduce street furniture / clutter. A Williams 15.08.2014
11/8/14	6.	Junction of Blenheim Crescent and Biscot Road.	Cars being parked on the pavement blocking the footway. Yellow lines cannot be enforced.	Stuart Jackson LBC Highways & Engineering	As per above restrictions are in place at this location. It is an issue for Parking Enforcement. There is a programme of refreshing yellow and this location will be investigated to see if this is required. A Williams 15.08.2014

Date of tour Biscot Ward	Ref	Location	Issue	Action – Referred to	Outcome
11/8/14	7.	Saxon Road/Biscot Road	Parking bays on both sides of the road. Traffic often coming to a standstill. Vehicle also unable to get out of the Co-op car park.	Stuart Jackson LBC Highways & Engineering	An investigation of parking problems in the Biscot area is scheduled for this financial year. This problem will be investigated but may result in the removal of parking bays on one side (which may prove unpopular). A Williams 15.08.2014
11/8/14	8.	Peri Peri Chicken, Saxon Road	Opening and serving until midnight and after. This is not within their permitted hours.	•Tony Ireland LBC Licensing •Steven Dibble Trading Standards •Laura Church Environment & Regeneration	Not a Trading Standards matter, Passed to Enforcement and Police to review. – Licensing. Aaron Wiltshire.
11/8/14	9.	Althorp Road/Biscot Road	Very odd how the contractors have refreshed the double yellow lines leading from Biscot Road into Althorp Road. See picture.	Stuart Jackson LBC Highways & Engineering	A repair was made at this junction that covered existing road markings. Therefore the lining has only been refreshed in the area of the repair. We have however, referred the issue to a highways inspector to see whether the rest of Althorp Road requires faded / worn road markings refreshed too. Ref 810351. S Jackson 18.08.2014

Date of tour Biscot Ward	Ref	Location	Issue	Action – Referred to	Outcome
11/8/14	9.	Dunstable Road from Nadeem Plaza to Hazelwood Crescent.	No pedestrian crossing apart from one by Barclays Bank.	Stuart Jackson LBC Highways & Engineering	We assume this relates to Hazelbury Crescent. There are 2 signalised crossing, and a number of courtesy crossings. A Williams 15.08.2014
11/8/14	10.	Lincoln Road	Make it all one way, not just part of it.	Stuart Jackson LBC Highways & Engineering	There have been no requests from residents, but this will be added to a priority list. A Williams 15.08.2014
11/8/14	11.	Highbury Road	Lots of fly-tipping taking place in the road and lots of rubbish at the very end of the road where the tree is planted. This location is overgrown with weeds.	Barry Timms LBC Parks Division	
11/8/14	12.	Birch Link. The grassed area opposite the rear of the Nadeem Plaza.	Could this area be looked at for extra parking?	Stuart Jackson LBC Highways & Engineering	There is no funding available for this, but this will be added to a priority list. A Williams 15.08.2014
11/8/14	13.	Outside 34. Leagrave Road. • H.T Travel	Large square dip in the pavement. Looks like a bin may have been located there at some stage.	Stuart Jackson LBC Highways & Engineering	Passed to highways inspector to investigate. Ref 810364. Tarmac patch to be placed 28 days from 21.08.2014. S Jackson 18.08.2014

Date of tour Biscot Ward	Ref	Location	Issue	Action – Referred to	Outcome
11/8/14	14.	The pedestrian railing to the side of Nadeem Plaza by the loading bay.	Badly damaged.	Stuart Jackson LBC Highways & Engineering	Passed to highways inspector to investigate. Ref 810374. Railing is very slightly bent but does not warrant replacing. S Jackson 18.08.2014
11/8/14	15.	Jalalabad Jame Majid, 36. Leagrave Road, Luton, LU4 8HZ	During Friday prayers the area is in ciaos due to the parking. Attendees of the mosque park all the way down the ramp and if there was an emergency it would be impossible for vehicles to get near to the area.	Luton & Bedfordshire Fire Service.	
11/8/14	16.	Alexandra Avenue	Road is cracking and lots of scabbing.	Stuart Jackson LBC Highways & Engineering	Passed to highways inspector to investigate. Ref 810376. The carriageway has some crazing, but this does not yet meet our criteria for repair. S Jackson 18.08.2014

Date of tour Biscot Ward	Ref	Location	Issue	Action – Referred to	Outcome
11/8/14	17.	Ward is being looke issues, particularly a parking schemes. The Ward Members to sit down with office	are that the whole of Biscot ed at in terms of Highways around road layout and a would like the opportunity cers from Highways & lans have been developed osal to consider.	Stuart Jackson LBC Highways & Engineering Alan Williams	There is an item in this year's highways works programme to investigate parking problems in various roads in the Biscot Area. This investigation may leads to other roads being included in the review of parking, but the review does not include the whole Biscot Ward. Councillors will be consulted in the normal fashion. A Williams 15.08.2014